



United Republic of Tanzania
OFFICE OF THE PRESIDENT
REGIONAL ADMINISTRATION AND LOCAL GOVERNMENT
ULANGA DISTRICT COUNCIL



Phone No: 023-2620311
Fax No: 023-2603007 / 311
Email: dmomahenge@gmail.com
MAHENGE / ULANGA
KUB: No: UDC / H / L / 1 / VOL / 11/149

HEALTH DEPARTMENT
P.O.BOX 4
15/02/2021

REGIONAL MEDICAL OFFICER
P.O.BOX 110
MOROGORO.

C/O
DISTRICT MEDICAL OFFICER
P.O.BOX 4
MAHENGE / ULANGA

KWIRO DISPENSARY INSPECTION REPORT.

Please refer to the headline above.

Introduction

Kwiro Dispensary is located in Vigoi Ward, Vigoi Division, Ulanga District. According to the 2012 population and housing census, the village is estimated to have a total population of 12,653. Kwiro Dispensary has been providing health services since the 1920's. Now the owners of the dispensary, which is a Catholic church in Mahenge State, have decided to upgrade their status and become a health center, sending their applications to the District Medical Officer. The main economic activities of the villagers are agriculture, labor and livestock. They have also been receiving health care from Mahenge Ulanga District Hospital, as well as the Kwiro dispensary owned by the Catholic Church in Mahenge State.

REASONS FOR INSPECTION

After submitting applications for the promotion of the Dispensary, the District Health Services Management Team (CHMT) went to inspect all the buildings that were designed to be a Health Center including the old buildings and new buildings.

The CHMT team went to inspect the buildings to see if the service could be installed in the area.

REVIEW

The outer part

- The area is large and large enough for the task.
- It is easily accessible, located near the road.

A. Inside

The building has many rooms designed for service delivery. These are Reception, Pharmacy,

B. Floor

Some rooms are fitted with tiles, and some are plastered with concrete and the walls and ceilings are whitewashed.

C. Water Access

Access to water is guaranteed from a private well.

D. Waste disposal

Waste incinerator and placenta pit are built approximately 35 meters from the clinic building. It is well-built with two doors and is set aside for waste disposal and incineration.

E. Operating room

After inspecting and resorting to the operating room, the team asked the Council Engineer to come and inspect and make recommendations based on a map of the Ministry of Health.

F. LABORATORY

An inspection of the Laboratory building was conducted to see if the building meets the criteria of the Health facility Laboratory.

The outer and inner part has room to give

Water supply is guaranteed

Toilets are available

Electricity is guaranteed

G. RCH

i. The inner part has enough space

ii. There are special rooms for pregnant women and Health Education

iii. There is a special vaccination room

iv. There is a special section for testing children

v. Water is available all the time

vi. The building has independent toilets.

H. DENTAL ROOM

It is large and sufficient for the service and has a reception section

They have also provided modern and adequate equipment for the service and there are two attendants.

I. SERVANTS

• **Doctors**

MD.1, AMO.1, C.O2.

• **Laboratory**

Lab tech 1, Lab Attendant 1.

• **Nurses**

RN 2, MATT 4

• **Dental**

Dental therapist 1, Dental Attendant 1

• **Guards**

There is 1 guard

After the audit, the team identified the following shortcomings:

- i). No harsh pit (pit l throw ashes)
- ii). There is no fence in the incinerator and placenta pit
- iii). There are only a few OPD rooms
- iv). The ward rooms are small and can accommodate only four beds
- v). All required water cookies
- vi). The staff council is not enough

RECOMMENDATIONS

Overall the building is complete and meets the criteria for providing Health services.

However the team recommended the following:

- I. Harsh pit dug immediately
- II. Prepare them for parking
- III. A fence around a sharp pit, a placenta pit and a garbage can be built
- IV. Fences should be erected in the suburbs and Mortuary
- V. We suggested adding staff in nursing and sleep zones
- VI. Laying a bridge to connect the original buildings with the new buildings.

TIMU YA WAKAGUZI

Na	JINA	CHEO	SAINI	TAREHE
1	Dr Ally Mjema	DMO	<i>A. Mjema</i>	15/2/2021
2	Dr. Nathalia Mtolera	PPP/FP	<i>N. Mtolera</i>	15/2/2021
3	Ezekia Chavala	Ag.DHO	<i>E. Chavala</i>	15.2.2021
4	Triphonia Mushi	DNO	<i>T. Mushi</i>	15/2/2021
5	Ally Said Juma	Ag.DLT	<i>A. Said Juma</i>	15.2.2021
6	Modestus Lupia	DDO.	<i>M. Lupia</i>	15.2.2021

Imethibitishwa na

M. Mwangi
 DISTRICT MEDICAL OFFICER
 P.O. BOX 4
 MATHENGE/ULANGA

Kaimu Mwangi Mkuu Wraya,

Nakala,

DED;Ulanga

Mmiliki wa Zahanati ya Kwiro.